

FIG. 1




FIG. 3




FIG. 2




Fig. 4




Fig. 5




Fig. 6




Fig. 9





Fig. 7

Fig. 8






FIG. 13





FIG. 11








FIG. 12



170




FIG. 18

FIG. 19





FIG. 19




FIG. 21




FIG. 22A




FIG. 22B

10007061 419074




FIG. 23

FIG. 24A




FIG. 24B




FIG. 24C








FIG. 24D








FIG. 29




FIG. 30




FIG 31




FIG. 32








[illegible]

FIG. 33



10007054-43001

Pressure



Time

FIG. 39

Pressure





Fig. 40 Time

10007064-43001

Pressure



Time

FIG. 41

FOOT 150000

Pressure




Fig. 42

Time

Pressure
FOOT = 1000





FIG. 43

FOOT PRESSURE




Time

FIG. 44

10007061-43001

Pressure



Time

FIG. 45

Pressure




FIG 46

Pressure





FIG. 47

Time

FOOT T507001

Pressure



Time

FIG. 48

10007001 113001
Pressure




FIG. 49

Time

10007000
Pressure




FIG. 5D

Time

10007061 Pressure




FIG. 52

Time

10007064-13004

Pressure




FIG 53

Time

Pressure




FIG. 54

Time